

	Type	L #	Hits	Search Text	DBs	Time Stamp	Components	Error Definition	Errors
1	BRS	L 1	451	(microchannel\$1 or microfluidic\$1 or microfabricat\$5 or micromachin\$5) and ((melt\$3 or fus\$3) same (diaphragm\$1 or membrane\$1))	USPAT; EPO; JPO; DERVENT	2004/06/14 09:10			0
2	BRS	L 2	187	(microchannel\$1 or microfluidic\$1 or microfabricat\$5 or micromachin\$5) and ((melt\$3 ) same (diaphragm\$1 or membrane\$1))	USPAT; EPO; JPO; DERVENT	2004/06/14 09:11			0
3	BRS	L 3	9519	422/\$.ccls. or 436/\$.ccls.	USPAT; EPO; JPO; DERVENT	2004/06/14 09:11			0
4	BRS	L 4	42	2 and 3	USPAT; EPO; JPO; DERVENT	2004/06/14 09:11			0
5	BRS	L 5	42	2 and 3	USPAT; US-PGPUB; EPO; JPO; DERVENT	2004/06/14 09:44			0

	Type	L #	Hits	Search Text	DBs	Time Stamp	Components	Error Definition	Errors
6	BRS	L 7	1	6057149.pn. and melt\$3 and diaphragm\$3	USPAT; US-PGPUB; EPO; JPO; DERWENT	2004/06/14 09:44			0
7	BRS	L 6	2	6057149.pn. and melt\$3	USPAT; US-PGPUB; EPO; JPO; DERWENT	2004/06/14 09:45			0